


instructions for barcode readers


HD-SL99




Baud rate 4800 bits




Baud rate 9600 bits




19200 hd-sl99




Baud rate 115200 bits




NONE parity set




EVEN parity set




ODD parity set




SPACE parity set



MARK parity set



Enable CTS/RTS



Disable CTS/RTS

