

instructions for barcode readers

HD610A



Factory reset



Interface USB Virtual COM



Add Enter Suffix



Cancel Enter



Continuous mode on



Manual mode



Sound on



Sound off



Baud rate 115200 bits



Baud rate 9600 bits

