

instructions for barcode readers

HD610A




Restablecimiento de fábrica

Factory reset



Interfaz USB virtual COM

Interface USB Virtual COM



Anadir Enter Sufijo

Add Enter Suffix



Cancel Enter

Cancel Enter



Modo continuo en

Continuous mode on



Modo manual

Manual mode



Sonido encendido

Sound on



Sonido apagado

Sound off



Velocidad en baudios 115.200 bits

Baud rate 115200 bits



Velocidad de baudios 9600 bits

Baud rate 9600 bits

