

instructions for barcode readers

HD610A



Retour aux parametres d'usine

Factory reset



Interface USB virtuel COM

Interface USB Virtual COM



Ajouter un suffixe

Add Enter Suffix




Annuler Entrer

Cancel Enter



Continuous mode on

Continuous mode on



Manual mode

Manual mode



Son sur

Sound on



Éteindre

Sound off



Baud rate 115200 bits

Baud rate 115200 bits



Baud rate 9600 bits

Baud rate 9600 bits

