

instructions for barcode readers

HD610A




Fabrieksinstellingen

Factory reset



Interface USB Virtual COM

Interface USB Virtual COM




Voeg toe Enter Achtervoegsel

Add Enter Suffix



Annuleer Enter

Cancel Enter



Continuumodus aan

Continuous mode on



Handmatige modus

Manual mode



Geluid aan

Sound on



Geluid uit

Sound off



Baudrate 115200 bits

Baud rate 115200 bits



Baud-snelheid 9600 bits

Baud rate 9600 bits

