

instructions for barcode readers

HD21



Sleep time after 10 sec



Sleep time after 20 sec




Sleep time after 5 min



Sleep time after 30 min



Shutdown after 10 sec



Shutdown after 15 min

